LABCAR Software Compatibility List V5.4.13

Valid From: March 2022

	V5.4.9 EE V3.7.9	V5.4.10 EE V3.7.10	V5.4.11 EE V3.7.11	V5.4.12 EE V3.8.0	V5.4.12 HF1 EE V3.8.1	V5.4.13 EE V3.8.2
Released:	Jun-19	Dec-19	Jul-20	Apr-21	Jul-21	Mar-22
Microsoft® Windows						
Windows 7 SP1 (64-bit)	✓	✓	✓			
Windows 8.1 (64-bit)	✓	✓	✓	2)	2)	2)
Windows 10 (64-bit)	3)	3)	3)	3)	3)	3)
LABCAR-RTPC						
V6.3.7 (64-bit OS)	✓					
V6.4.0 (64-bit OS)		✓				
V6.4.1 (64-bit OS)			✓			
V6.5.0 (64-bit OS)				✓		
V6.5.1 (64-bit OS)					✓	
V6.5.2 (64-bit OS)						✓
INCA						
V7.2.4	2)					
V7.2.5	2)					
V7.2.6	2)					
V7.2.8	2)					
V7.2.9	2)					
V7.2.10	2)					
V7.2.12	✓					
V7.2.13	✓					
V7.2.14		✓				
V7.2.15		✓				
V7.2.16			✓			
V7.2.17			✓			
V7.3.0				2)		
V7.3.1				2)		
V7.3.2				✓		
V7.3.3				✓		
V7.3.4				✓		
V7.3.5					✓	✓
V7.3.6						✓
V7.3.7						✓
HSP						
V11.13.0	✓					
V11.14.1		2)	2)	2)	2)	2)
V11.14.2		✓	2)	2)	2)	2)
V11.15.0		✓	2)	2)	2)	2)
V12.0.0			✓	2)	2)	2)
V12.1.0			✓	2)	2)	2)
V12.2.0				2)	2)	2)
V12.3.0				2)	2)	2)
V12.4.0				✓	2)	2)
V12.5.0					✓	2)
V13.0.0						✓
LABCAR-AUTOMATION						
V4.2.3	✓	✓	✓			
MATLAB® /Simulink						
R2015b	1)					
R2016a	✓	✓	✓	✓	✓	✓
R2016b	✓	✓	✓	✓	✓	✓
R2017a	✓	✓	✓	✓	✓	✓
R2017b	✓	✓	✓	✓	✓	✓
R2018a	✓	✓	✓	✓	✓	✓
R2018b	✓	✓	✓	✓	✓	✓
R2019b		✓	✓	✓	✓	✓
R2019a	✓	✓	✓	✓	✓	✓
R2020a			✓	✓	✓	✓
R2020b						✓
R2021a						✓
R2021b						✓
ASCET MD						
V6.0.1 HF3 + HF8 + HF10	✓	✓	✓	✓	✓	✓
V6.2.0HF1	✓	✓	✓	✓	✓	✓
V6.2.1HF3	✓	✓	✓	✓	✓	✓
V6.4.2	✓	✓	✓	✓	✓	✓
Tesis Dynaware						
veDyna 3.11 Rel. 3.4	✓	✓	✓	✓	✓	✓
EB tresos Busmirror						
V4.8.1	5)	5)	5)	5)	5)	5)
V4.9.0	5)	5)	5)	5)	5)	5)
V4.10.1	5)	5)	5)	5)	5)	5)
V4.10.2	5)	5)	5)	5)	5)	5)
V4.13	5)	5)	5)	5)	5)	5)
V4.14	5)	5)	5)	5)	5)	5)
V4.15	5)	5)	5)	5)	5)	5)
V4.16	✓	✓	✓	✓	✓	✓
V4.16.1	✓	✓	✓	✓	✓	✓
V4.16.2		✓	✓	✓	✓	✓
V4.17.1			✓	✓	✓	✓
V4.17.2			✓	✓	✓	✓
V4.17.3			✓	✓	✓	✓
V4.17.4			✓	✓	✓	✓
V4.17.5			✓	✓	✓	✓
V4.18.1			✓	✓	✓	✓
V4.18.2			✓	✓	✓	✓
V4.18.3		✓	✓	✓	✓	✓
V4.19.5				✓	✓	✓
V21.5.0				✓	✓	✓
V21.6.0						✓
V21.10.2						✓
V21.10.3						✓

1) MATLAB® supports both 32-bit and 64-bit for 2015b and supports 64-bit versions only from R2016a onwards.
2) The related version was not explicitly tested with the corresponding LABCAR-OPERATOR version.
3) Windows 10 Version 20H2 is used for verifying compatibility. LABCAR-OPERATOR was not explicitly tested with other versions of Windows 10. If there are any issues with specific versions of Windows 10, please contact us with problem report via Support Team.
4) INCA v7.2.10 is tested for compatibility with LCO v5.4.8. However, when INCA v7.2.10 is installed in a PC where LCO v5.4.8 is already installed, ETAS BOA component v2.19 needs to be explicitly upgraded. Please refer to LCO Release Notes Page no. 24 mentioned section below on how to upgrade.
    - INCA 7.2.10 Update causes target server crash when Labcar IP 5.4.8 is installed.
5) EB tresos Busmirror is not compatible with Windows 10 Platform.

Note: Parallel installation of both COSYM V2.x and LCO V5.4.13 on a same Windows machine is not supported.